

Notice to Navigation Interests

Detroit District P.O. Box 1027 Detroit, MI 48231-1027 (313) 226-6796 FAX - (313) 226-3519

Notice No. L01-08 Date: 8 MARCH 2001

Waterway: LAKE MICHIGAN Location: WISCONSIN

CELRE-ET-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL GREEN BAY HARBOR


- 1. Condition surveys performed within the Federal navigation channel at Green Bay Harbor, Wisconsin during June October 2000, indicate shoaling as shown on the following sheets.
- 2. Vessel operators should use caution when navigating within this area.
- 3. All inquiries should be addressed to CELRE-ET-OT-T and should refer to Notice to Navigation Interests No. L01-08. Internet address: http://huron.lre.usace.army.mil/OandM/o&m.html

RICHARD J. POLO, JR. Lieutenant Colonel, U.S. Army District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2001.





AREA 6

GREEN BAY HARBOR, WISCONSIN

CONDITION OF CHANNEL

ISSUED: 8 MARCH 2001


U.S. Army Engineer District, Detroit

The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that

Shoals indicate least available depth below I.G.L.D.

Surveys taken: JUNE, JULY, OCTOBER 2000

0green6.bmp



CONDITION OF CHANNEL

ISSUED: 8 MARCH 2001

U.S. Army Engineer District, Detroit

0green7.bmp

general conditions existing at that

considered as indicating the

indicated and can only be

Surveys taken: JUNE, JULY 2000